

Kansas Department on Aging

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:  <b>N046057</b>	(X2) MULTIPLE CONSTRUCTION A. BUILDING: _____  B. WING: _____	(X3) DATE SURVEY COMPLETED  <b>12/04/2013</b>
NAME OF PROVIDER OR SUPPLIER  <b>ABERDEEN VILLAGE</b>		STREET ADDRESS, CITY, STATE, ZIP CODE <b>17500 WEST 119TH STREET OLATHE, KS 66061</b>		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
S 000	INITIAL COMMENTS  The following citations represent the findings of a Health Resurvey.	S 000		
S1174 SS=D	26-40-303 (2)(a)(i)(ii)(iii) P E - Door monitoring system  (2) Door monitoring system. The nursing facility shall have an electrical monitoring system on each door that exits the nursing facility and is available to residents. The monitoring system shall alert staff when the door has been opened by a resident who should not leave the nursing facility unless accompanied by staff or other responsible person.  (A) Each door to the following areas that is available to residents shall be electronically monitored:  (i) The exterior of the nursing facility, including enclosed outdoor areas;  (ii) interior doors of the nursing facility that open into another type of adult care home if the exit doors from that adult care home are not monitored; and  (iii) any area of the building that is not licensed as an adult care home.  This REQUIREMENT is not met as evidenced by: K.A.R. 26-40-303 (h)(2)(A)(i)(ii)(iii)  The facility reported a census of 56 residents. Based on observation, and interview the facility failed to maintain an electrical monitoring system	S1174		

LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE

TITLE

(X6) DATE

Kansas Department on Aging

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:  <b>N046057</b>	(X2) MULTIPLE CONSTRUCTION A. BUILDING: _____  B. WING: _____	(X3) DATE SURVEY COMPLETED  <b>12/04/2013</b>
NAME OF PROVIDER OR SUPPLIER  <b>ABERDEEN VILLAGE</b>		STREET ADDRESS, CITY, STATE, ZIP CODE <b>17500 WEST 119TH STREET OLATHE, KS 66061</b>		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
S1174	<p>Continued From page 1</p> <p>on two exit doors.</p> <p>Findings included:</p> <p>- Observation during tour on 11/21/13 at 9:35 A.M. revealed the exit door on the end of the Northgate hallway did not alarm when opened.</p> <p>Observation during tour on 11/21/13 at 9:35 A.M. revealed the exit door on the end of the Whispering Meadows hallway did not alarm when opened.</p> <p>Interview with maintenance staff X on 11/21/13 at 10:00 A.M. stated the doors alarmed if a resident tried to exit who had a wanderguard bracelet on. Otherwise the door opened when the keypad code was entered and would not alarm.</p> <p>Interview with administrative maintenance staff Y on 11/21/13 at 10:05 A.M. stated the doors should alarm when they were opened.</p> <p>Interview with administrative staff A on 11/26/13 at 4:04 P.M. stated he/she was unaware the doors to the outside of the facility needed to be alarmed since the keypad was in place.</p> <p>The facility failed to maintain a monitoring system on the exit doors.</p>	S1174		